

DXY METAL INDUSTRIES CORPORATION

32100 STEPHENSON HWY., MADISON HEIGHTS, MICHIGAN 48071 (313) 583-9300

August 17, 1977

Douglas Aircraft Company 3855 Lakewood Boulevard Long Beach, CA 90846

Attention: Mr. M. J. Veneroso

Dear Mr. Veneroso:

Your letter of May 23, 1977, addressed to our Buena Park facility was forwarded to the writer. Unfortunately, it arrived while I was out due to illness and has been buried with other work awaiting the time that I could catch up with it.

The questions concerning Oxyvate 301 B-30 will be handled by Mr. Winkler of the Udylite Division.

The remaining items are not listed by the DOT in section 172101 CFR-49 and do not meet the definitions for hazardous materials.

None of these items have a flash point.

The items referred to are:

Den 2988

Accelerator, 170

Accelerator, 171

Parcolene® Neutralizer 21 Den 3/76-/

Neutralizer, 270

Neutralizer, 270

Parco® Cleaner 342

Den 2990

Den 2990

Den 2990

There is one peculiarity in the above products, and that has to do with Accelerator, 170. This product is sodium bifluoride. This product is not rated as a hazardous product by DOT for shipment within this country either by surface or by truck, however, the IATA does list it as a Poison B with an IATA number 2208.

If there are any further questions, please contact the writer.

Yours truly,

PARKER DIVISION OXY METAL INDUSTRIES CORPORATION

W. R. Cavanagh, Manager Technical Services

WRC:so